

Tool Kit, Explosive Ordnance, Response Kit

SC: **1385-95-A25**
NSN: **1385-01-487-8701**
LIN: **T00280**

System Description

"NSN 1385-01-487-8701 replaces old NSN 1385-01-267-8116. The Response Kit is subject to the Warranty /Replacement Program. This all components to this kit should be reset by the using unit via the Warranty/Replacement Program. Contact Item manager to report battle loss of kit if necessary and request disposition."

This system is not currently in reset.

Reset Type

Reset Work (Field Level) - Work performed to correct equipment faults that are performed at the ORG/DS level; performed by unit level soldiers, augmented by contractor as required.

Reset Strategy

NSN 1385-01-487-8701 replaces old NSN 1385-01-267-8116. The Response Kit is subject to the Warranty /Replacement Program. This all components to this kit should be reset by the using unit via the Warranty/Replacement Program. Contact Item manager to report battle loss of kit if necessary and request disposition.

Reset Procedures

- Replace worn, broken, missing components IAW supply catalog.
- Reorder consumables IAW SC.

Reset Responsibility

Unit

Reset Location

This system is not currently in reset.

- Contact Information -

877.4.PMSKOT (877.476.7568)
rock-pm-skot@conus.army.mil